STANDARD OPERATING PROCEDURE – 6004

BIOLOGICAL HAZARDS

PURPOSE: To establish a standard operating procedure for the identification and management of biological hazards in Supply Processing & Distribution (SPD).

POLICY: To reduce or eliminate Biological Hazards in the workplace.

RESPONSIBILITY: The person with responsibility for SPD functions and each person assigned to the SPD area.

PROCEDURE:

- 1. All blood and body fluids are considered to be biological hazards.
- 2. Prevention of blood and body fluids reaching any employee's potential portal of entry in normal performance of their duties is accomplished through the use of Personal Protective Equipment (PPE):
 - Long cuffed rubber/vinyl decontamination specific gloves (not latex exam gloves)
 - Head/Hair cover
 - Face/eye shield (or goggles/mask)
 - Long sleeved impervious gown/jumpsuit
 - Impervious shoe covers or boots (knee high)
- 3. Hepatitis B vaccine will be provided for all staff assigned to SPD. The employee has the right to refuse this vaccine by signing a waiver.
- 4. All soiled supplies, instruments, and equipment are transported in a closed or covered cart or container. Covers will be impervious.
- 5. Gloves must be worn for handling soiled equipment and then discarded. Gloves are not worn between pick up points.
- 6. All personal protective equipment (PPE) is put on before entering the decontamination area. PPE must not to be stored inside the decontamination area.
- 7. All PPE is removed prior to leaving the decontamination area. Scrubs must be changed when leaving the decontamination area. A shower is recommended at the end of the decontamination shift or if employee is changing assignment.
- 8. Employees injured must report to a supervisor immediately then report to Employee Health. CA-1 and 2162 forms are completed through ASISTS.

9. Each personnel assigned to SPD (or area where SPD type functions take place) is responsible for reporting safety hazards to a supervisor or a responsible program official.

Reference: VA Handbook 7176 – Supply, Processing and Distribution Operational Requirements